

## 16200 - Combi5xx - Combi422 Series - New Fw v 2.12

### Modifications (vs Fw v 1.24)

- HARM: now App HT Analysis displays correctly also fundamental value (100%)

### Bugs fixed (vs previous Fw release)

- HARM. values Fixed bug about harmonic order indicated when calling this page for 1st time
- LOOP: fixed bug about data type indication (direct mode)

### Additional Notes:

**Note : This Fw release requires latest Topview version**

## 16200 - Combi5xx - Combi422 Series - New Fw v 2.11

### Modifications (vs previous Fw release)

- Ra No Trip Loop: Improved Test immunity against electrical noise
- DV%: Z1 value was lost after instrument turning off. Now Z1 value is kept after turning off/on the instrument.
- General settings: introduced LCD Contrast adjustment

### Bugs fixed (vs previous Fw release)

- none

### Additional Notes:

**Note : This Fw release requires latest Topview version**