

90550 - FULLTEST3 - New Fw v. B45.M23.V09

Modifications (vs previous Fw release)

- none

Bugs fixed (vs previous Fw release)

- IPSC calculation corrected in LOOP L/L and IMP L/L measurements, limits settings kA, I2t and TRIP. CURR. UnomL-L used in calculation instead of wrong UnomL-N.
- bug removed in Dielectric current adjustment (no changes for the end user)

90550 - FULLTEST3 - New Fw v. B44.M21.V09

Modifications (vs previous Fw release)

- none

Bugs fixed (vs previous Fw release)

- DIELETRIC: Fixed bug about Ramp Test 50% or 75%. TIMER value was not considered any longer. Now fixed