

15700 - PQA819 - PQA820 Series - New Fw v 1.15

Modifications (vs previous Fw release)

- Fixed rare system crash with mains frequency = 60Hz

Bugs fixed (vs previous Fw release)

- Managed new internal WiFi module