

13010 - PQA924 - New FirmWare V1.04

Bugs fixed (vs previous FW 1.03 release)

- Inrush current: Fixed maximum number of recordable events
- Inrush current: Fixed the range of the inrush current, now it is consistent with the chosen clamp full-scale
- Improved instrument reading battery-recharging status
- Fixed voltage reading problem in 3P3W with power-supply connected (A0080)

Modifications (vs previous FW 1.03 release):

- None

Additional Notes:

- None

13010 - PQA924 - New FirmWare V1.03

Bugs fixed (vs previous FW 1.02 release)

- General Improvements and bug fixes

Modifications (vs previous FW 1.02 release):

- New strings and changes

Additional Notes:

- None

13010 – PQA924 - New Fw v 1.02

Bugs fixed (vs previous FW 1.01 release)

- General Improvements and bug fixes

Modifications (vs previous FW 1.01 release):

- General Improvements and bug fixes

Additional Notes:

- None

13010 – PQA924 - New Fw v 1.01

Bugs fixed (vs previous FW 1.00 release)

- General Improvements and bug fixes

Modifications (vs previous FW 1.00 release)

- General Improvements and bug fixes

Additional Notes:

- None