


















OPTIONALES ZUBEHÖR

MULTIFUNKTIONS- MESSGERÄTE									
MODELLE	HT96U	HT97U	HT98U	HP30C2	HP30C3	HP30D1	HTFLEX 3003	HTFLEX 33	F3000U
GSC57	•	•		•	•		•		
GSC60	•	•	•	•	•	•			
I-V400W / I-V500W									
COMBI G2 · COMBI G3	•	•	•	•	•				
COMBI420	•	•		•	•				
COMBI419	•	•		•	•				
SPEED418									
M72	•(*)	•(*)	•(*)	•(*)	•(*)				
M73	•(*)	•(*)	•(*)	•(*)	•(*)				
M74	•(*)	•(*)	•(*)	•(*)	•(*)				
M75	•(*)	•(*)	•(*)	•(*)	•(*)				
<b>NEU</b> JUPITER	•(*)	•(*)	•(*)	•(*)	•(*)				•
<b>NEU</b> MERCURY	•(*)	•(*)	•(*)	•(*)	•(*)				•
ISO410									
PQA820***	•	•	•	•	•	•			
PV CHECKs	•	•	•	•	•				
FULLTEST3	•								
SOLAR300N	•	•	•	•	•	•		•	
<b>NEU</b> SOLAR I-Ve	•	•	•			•			
PQA823	•	•	•	•	•	•			
PQA824	•	•	•	•	•	•			
VEGA78	•	•	•	•	•	•			

(\*) Mit als optional erhältlichem Zubehör **NOCANBA**; (A) Mit als optional erhältlichem Zubehör **ABNACON** (\*\* Zange nur bedingt für Leistungsmessung geeignet. (\*\*\*) ACONBIN Adapter für Verbindung zu PQA820 erforderlich (siehe Seite 119)

OPTIONALES ZUBEHÖR

ZANGEN UND MULTIMETER								
MODELLE	T10	TK107	TK108	TK109	TK110	TK111	B80	SP6085
HT 211	•	•	•	•	•	•	•	
<b>NEU</b> JUPITER								•
HT710, HT712								
HT4020, HT4022							•	
HT9012, HT9019, HT9020, HT9022							• (HT9012)	•
HT9021, HT9014, HT9015	•	•	•	•	•	•	•	• (HT9021)
HT401	•	•	•	•	•	•		•
HT701, HT8100								•
HT60er Serie + MERCURY	•	•	•	•	•	•		•
Ironmeter							•	
HT6, HT8, HT9								•

(\*\*) Nur HT63, HT64, MERCURY